50X1-HUM Sanitized Copy Approved for Release 2011/05/17: CIA-RDP82-00457R010500400009-6 CENTRAL INTELLIGENCE AGENCY REPORT INFORMATION REPORT CD NO. COUNTRY DATE DISTR. Germany (Russian Zone) 12 Mar 52 NO OF PAGES SUBJECT Hochseeschiffbau Warnow-Werft, Warnemunde PLACE OF ENCLS. **ACQUIRED** 50X1-HUM SUPPLEMENT TO DATE OF INFO. REPORT THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN 1 IS BEARING OF FITTE 10, SECTIONS 708 AND 704. OF THE U.S. CODY, AS AREHOED. ITS TRANSUISSION OR REVEL-ATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTRORIZED PERSON IS PROPRIETED BY LAW IN THE REFROUNCTION OF THIS FORM IS PROVIBILITED. THIS IS UNEVALUATED INFORMATION 50X1-HUM 

## 1. S.S. RUS

50X1-HUM

- a. In spite of stren ous efforts on the part of the Dockyard Directorate to get this vessel finished on time, it is now not expected to be completed

  This delay is largely caused by the unexpected failure of its newly installed engines to function as anticipated.
- b. The two main diesel engines were uncoupled from the mainshaft and given a trial run, which showed the following weaknesses two cylinders on the port engine did not work at all; the starboard motor developed a major oil leak, and there was too much play on the engine bed requiring a fresh setting (neue Millimeter Unterlager). The ten workmen from the MAN factory at Augsberg are still in the dockyard and are supervising the repairs to the engines which have been dismantled again and taken out of the ship.
- c. Although the former German degaussing girdle switchboard has been overhauled with new fuses, copper coils, isolators and distributors, and fitted and replaced in the ship, no preparations have been made for the fitting of a degaussing girdle. It was observed that, unlike the switchboard fitted into the ASIA last year, the switchboard now in the RUS has leads for more lines of cable as each switch box has 16 wire leads fitted to it.

## 2. S.S. SOVIETSKI SCYUZ

Work continues on board this vessel. The engine room is now finished and is reacy for the installation of the engines. The lowest hold, whose bulkhesds will be of wood, is now being constructed. Work is under way in the construction office of the dockyard on the plan for the fitting of cable and power leads. As yet nothing has been announced regarding the fitting of a degaussing girdle.

COMPLIBITAL

1	× .	CLASSIFICATION	SECRET/CONTROL - U	SECRET/SONTROL U.S. OFFICIALS ONLY		
STATE	X MAVY	X NSRB	DISTRIBUTION	8 8 0 8 2 2 1   1   1   1   1   1   1   1   1		
ARMY	X AIR	X FBI		He Glange St. Car S. [7]		
				Declary Sed		
				50X1-HUN		

## SECRET/CONTROL - U.S. OFFICIALS ONLY

## CENTRAL INTELLIGENCE AGENCY

-2-

EOV1 LILIM

		SUX I-HUIVI					
3.	S.S.	· YIKUTIA					
	is a mone	k continues on board. The final plan for the interior of this vessel still not in the hands of the repair gang working on board. At the ent deck sections are being fitted. In connection with this construction, lan of the former vessel (now the SIBIR), which was fitted in this dockyard is being used.	50X1-HUM 50X1-HUM				
<u>4</u> .	S.E.	• ADMIRAL NAKHIMOV	0X1-HUM				
	mer.	this former steamer came to Warnow-Werft nemunde under its own steam with a Russian crew of between 40 and 50. The vessel is due for a thorough overhaul as she is very badly in d of repairs. Repair work is at present taking place on her boilers on the removal of badly damaged cables and power lines. The main	50X1-HUM 50X1-HUM				
	swi.	tchboard for the de-Gaussing girdle has already been removed.	50X1-HUM				
		The de-Gaussing girdle around the ship however, not yet been removed. This girdle appears to be new and is very good condition.	50X1-HUM				
5.	Min	esweepers					
	a。	These vessels are still apparently based at Warnemunde and have been carrying out exercises both on sea and in the Breitling between Rostock and Warnemunde. Most of their exercises consist of sailing in pairs some 25 meters apart. No minesweeping equipment has been observed in these manoeuvres.	50X1-HUM				
-	b₀	two of these vessels carried out firing practice some three sea miles north of Warneminde. Firing took place with what appeared to be small calibre guns firing bursts of approximately 15 rounds each time. The bursts appeared tc50X1-be fired with incendiary ammunition and were aimed up in the air although no target could be seen from the land. When the vessels returned to harbor, each boat gave the following morse signals with a shutter before entering:  dot dot dot dash, two minute interval, 50X1-HL					
		dot dash dot dot.  Some thousand meters off the harbor entrance, one vessel then fired a green signal rocket.					
6.	Nava	al motor vessels (KT class)					
	side obse	se vessels are still moored close to the shore on the Markgraffenheide e of the main channel close to the former seaplane base. They have been erved carrying out sailing practice with up to four boats travelling east between 10 and 15 meters apart. No firing practice or special occurres have been seen.					
7.	Ne.4	New ways					
•		two new ways under construction at the southern edge of the dockyard a are expected to be finished	50X1-HUM				

SECRET/CONTROL - U.S. OFFICIALS ONLY